CERAMENT™|BONE VOID FILLER

Preparation of paste







Transfer C-TRU solution to CMI and detach

MIX II


6-8 Transfer paste to ID-syringe & remove red plunger stop


0


30s


~1min





















www.bonesupport.com



Filling of the bone defect (void/gap) - 3 different options



All timelines are calculated from the Start of Mixing and vary slightly depending on product use



or Molded with use of Bead Mold Trays**



^{*} NOTE: Do not manipulate or touch extruded paste unnecessarily before initiation of molding.



^{**} Bead Mold not included in pack.